

## 5210-COV







MARK AND DRILL (3) 3/16 DIA. HOLES 7/8 DEEP. 19018 ANCHORT 3 PROVIDED 1015980 SPACER

PRODUCT DIMENSIONS

## CLEANING INSTRUCTIONS

RINSE COVER WITH WATER TO REMOVE ABRASIVE DUST AND DIRT.

WASH WITH SOAP OR MILD DETERGENT, USING A SOFT CLOTH (DO NOT SCRUB)

RINSE ONCE MORE, THAN DRY WITH A SOFT CLOTH OR CHAMOIS.

TO REMOVE GREASE OR WET PAINT, RUB GENTLY WITH A CLOTH WETTED THOROUGHLY WITH NAPHTHA, THAN WASH AND RINSE. (DO NOT USE RAZOR BLADES).


-19039 SCREWS


(6 X 1 1/4)

-3 PROVIDED

10283 COVER ASM.

101598 GASKET-INSTALL AFTER-COVER ASM. AND SPACER HAVE BEEN SECURELY FASTENED. TOP EDGE OF GASKET MUST BUTT AGAINST BOTTOM OF SPACER AS SHOWN. -





MAKE SURE SPACER IS INSTALLED AS SHOWN WITH MOUNTING HOLES BELOW CENTER LINE.

NOTE: IF WEATHER PROTECTION IS NOT REQUIRED, DISCARD GASKET AND SPACER, THEY ARE NOT NEEDED.

DORTRONICS SYSTEMS, INC. 1668 Sag Harbor Tpke., Sag Harbor, NY 11963 Tel. (631) 725-0505 • Fax (631) 725-8148

5210/COV SWITCH COVER